REG Geismar Inspection documentation LOG

No	Dated	Document Description and reference to Checklist item.
1	02/24/16	Tier Two Report
2	2014 rev	WCS Circle map (pg.4, #27)
3	07/29/14	Consequences of Deviation (pg 8; #15)
4	various	Training Certificates (pg 9; #22)
5	07/09/10	Pressure Relief Valve Test Report (pg 9, #27)
6	06/15/15	Annual Fire Sprinkler System Inspection Report (pg 9; #30)
	•	
•	Ý	
		,
	٠ ،	
	•	



TIER II Facility Report LOUISIANA CHEMICAL NETWORK

Click your browser's "Print" icon to print this page.

```
* * * Wed Feb 24 06:41:49 CST 2016 * * *
* * * Facility Identification * * *
_______
                 REG GEISMAR, LLC
Facility Name
Facility ID
                  47728
Facility Type
                 Fixed
Physical Address 36187 HWY 30
                  GEISMAR LA, 70734
                  ASCENSION PARISH
Latitude
                  30.201975
Longitude
                  -90.009401
Mailing Address
                  PO BOX 599
                  GERISMAR LA, 70734
Telephone
                  225-744-1302
Reporting Period
                  January 1 to December 31, 2015
Status
                  Active
NAICS Code
                  324110
SIC Code
                  2869
Dun & Bradstreet # 829825178
TRI ID
                  7073WDYNMC36187
                  100000210611
RMP ID
------
* * * Owner Information * * *
               REG GEISMAR, LLC
Company Name
Mailing Address
                  PO BOX 599
                  GEISMAR LA, 70734
Phone
                  225-744-1300
Fax
                   225-673-6235
                  PETER.GUAY@REGI.COM
Ema<sub>1</sub>l
* * * Emergency Contact * * *
Name
                  TROY S HARRIS
                   EHS COORDINATOR
Title
Phone
                   225-744-1316
24Hr Phone
                  225-744-1300
Pager
Fax
Cell Phone
                   225-252-3250
                  TROY.HARRIS@REGI.COM
* * * Emergency Contact * * *
                HOWARD R WIKLINSON
Name
Title
                   EH&S COORDINATOR
Phone
                   225-744-1306
24Hr Phone
                   225-715-4550
Pager
Fax
                   225-715-4550
Cell Phone
Email
                   TROY.HARRIS@REGI.COM
* * * Filing Information * * *
# Chemicals
                   R
Number of Employees No
less than or equal
to 9?
Annual Gross
                   No
Receipts under
Two Million?
# Facilities
Exemptions
                   None
Amount
                   65.00
Invoice #
                   28965838
```


1

```
Pressure
              Ambient
              Ambient
Temperature
Location
              TANK FARM
Confidential
              No
Location
_____
Pressure
              -SEL
Temperature
              -SEL
Location
Confidential
              Νo
Location
        ......
Pressure
          -SFI
Temperature
              -SEL
Location
Confidential
              No
Location
Pressure
            -SEL
              -SEL
Temperature
Location
Confidential
              No
Location
..........
          -SEL
Pressure
Temperature
              -SEL
Location
Confidential
Location
Pressure
             -SEL
Temperature
              -SEL
Location
Confidential
              No
Location
             -SEL
Pressure
Temperature
              -SEL
Location
Confidential
Location
-----
Pressure
           -SEL
Temperature
              -SEL
Location
Confidential
              No
Location
_____
* * * Chemical Mixture Description * * *
-----
Trade Name
              RENEWABLE LIQUEFIED PETROLEUM GAS
              LIQUEFIED PETROLEUM GAS
Common Name
             Gas
Chemical State
Last Reviewed Date 02/23/2016
* * * EPA Information * * *
Trade Secret &
              No
Approved by EPA?
* * * Mixture Components * * *
Proper Chemical PROPANE
                      67%
CAS#
               74986
Proper Chemical
               ISO BUTANE
CAS#
               75285
                      18%
Proper Chemical
               NORMAL BUTANE
CAS#
               106978
                      10%
Proper Chemical
               ISOPENTANE
CAS#
               78784 3%
 * * * Hazards * * *
Physical
               Fire
               Sudden Release of Pressure
```

Reportable Quantity 100 Lbs.

```
* * * Inventory
Max Daily Amount
                9999
Avg Daily Amount
                74999
                90
Days On Site
* * * Storage Types and Storage Locations * * *
Container Type(s) Above Ground tank
Pressure
                Greater than ambient
Temperature
                Amb1ent
                TANK FARM
Location
Confidential
Location
      .______
                -SEL
Pressure
Temperature
                 -SEL
Location
Confidential
                 No
Location
______
Pressure
                -SEL
                 -SEL
Temperature
Location
Confidential
               No
Location
            -SEL
Pressure
Temperature
                 -SEL
Location
Confidential
                 No
Location
Pressure
                 -SEL
                 -SEL
Temperature
Location
Confidential
                 No
Location
Pressure
                -SEL
Temperature
                 -SEI
Location
Confidential
                 No
Location
Pressure
                -SEL
Temperature
                 -SEL
Location
Confidential
                 No
Location
Pressure
                 -SEL
                 -SEL
Temperature
Location
Confidential
                 No
Location
* * * Chemical Mixture Description * * *
                 RENEWABLE NAPHTHA
Trade Name
Common Name
                 NAPHTHA
             Liquid
Chemical State
Last Reviewed Date 02/23/2016
 * * * EPA Information * * *
Trade Secret &
Approved by EPA?
 * * * Mixture Components * * *
 Proper Chemical
                 2,2,3-TRIMETHYLBUTANE
 CAS#
                 464062
 Proper Chemical
                 2,2,3-TRIMETHYLPENTANE
 CAS#
                 564023
 Proper Chemical
                 2,3-DIMETHYLBUTANE
 CAS#
                 79298
                          12%
```

Proper Chemical 2,4,4-TRIMETHYLHEXANE



Worksheet

Page: 140

Company: Renewable Energy Group (REG)

Facility: REG, Geismar

Table of contents


Session: (2) 7/29/2014

Node: (140) LPG - YELLOW

Intention: Pressure: 130 psig Temperature: Ambient Phase: Liquid & Vapor Flow: 12 GPM

Drawings: 60-0008 REV 8 Components: Vessel 60-V-6028

Components, vesser o								
DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS
1982. Low/No Flow	1982.1. Pumps are down when they should run	Delay in truck loading - Operational issue only						•
	1982.2. Tank is empty	Potential pump damage with seal	LT-6023 provides low level alarm	2	E	TR		
		fire - 2,1,2	LT-6012 provides low level alarm					
	1982.3. HV-6001 or manual valves are blocked between the tank	Potential pump damage with seal fire - 2,1,2	Double seal pump design is resistant to atmospheric leakage	2	D	TR		
	and the pumps		LEL monitors in area					
			Fire suppression equipment is available					
1983. More/High	1983.1. No							



AMERICAN PETROLEUM INSTITUTE INDIVIDUAL CERTIFICATION PROGRAMS

API Individual Certification Programs certifies that

David S. Thoman

has met the requirements to be a certified

API-570 Piping Inspector

Certification Number 1336

Original Certification Date January 31, 1997

Current Certification Date June 30, 2013

Expiration Date June 30, 2016

Tina Briskin Manager, Individual Certification Programs



API Individual Certification Programs certifies that

David S. Thoman

has met the requirements to be a certified

API-510 Pressure Vessels Inspector

Certification Number

Original Certification Date

Current Certification Date

January 31, 2015

Expiration Date

January 31, 2018

Manager, Individual Certification Programs



AMERICAN PETROLEUM INSTITUTE INDIVIDUAL CERTIFICATION PROGRAMS

API Individual Certification Programs certifies that

Christine Anne Simmons

has met the requirements to be a certified

API-570 Piping Inspector

Certification Number

53963

Original Certification Date

July 31, 2014

Current Certification Date

July 31, 2014

Expiration Date

July 31, 2017

Tina Briskin

Manager, Individual Certification Programs



AMERICAN PETROLEUM INSTITUTE INDIVIDUAL CERTIFICATION PROGRAMS

API Individual Certification Programs certifies that

David S. Thoman

has met the requirements to be a certified

API-653 Aboveground Storage Tanks Inspector

Certification Number 1469

Original Certification Date September 30, 1994

Current Certification Date September 30, 2015

Expiration Date September 30, 2018

Tina Briskin

Manager, Individual Certification Programs



AMERICAN PETROLEUM INSTITUTE

API Individual Certification Programs certifies that

Christine Anne Simmons

has met the requirements to be a certified

API-653 Aboveground Storage Tank Inspector

Certification Number

Original Certification Date

January 31, 2016

Current Certification Date January 31, 2016


Expiration Date

January 31, 2019

ina Briskin

Manager, Individual Certification Programs





AMERICAN PETROLEUM INSTITUTE

Individual Certification Programs: ICP™

API Individual Certification Programs certifies that

Christine Anne Simmons

has met the requirements to be a certified

API-510 Pressure Vessels Inspector

Certification Number:

54963

Original Certification Date

November 30, 2014

Current Certification Date

November 30, 2014

Expiration Date

November 30, 2017

Tina Briskin

Manager, Individual Certification Programs







New Pressure Relief Valve Test Report

S3-Six Sigma Service Type: SRV

Birth # 002ECN

Date Friday, July 09, 2010

Warehouse Date-Time 2009/10/29-10 00 Ship Date-Time 2009/11/02-8 00

Owner Dynamic Fuels Plant Geismar, LA Account # 30657 PO# 4506429249

Tag Number	PSV-6019	Location		Other Tag Data	PROJ EN0423	3
Most Recent	Yes (Relief Valve)	<u>Unit</u>		Client Stock#		
Manufacturer	Consolidated	Valve Size & Orifice	4 00 P 6 00 = 6 38 IN^2	In/Outlet Rating	300# RF / 150	#RF
Model Number	1910-00PC-2-CC-MS-31-RF-GS-H	IP S/N	SA49635	Cap Type	Screwed Cap	
Soft Seat Mat'l	N/A	Soft Seat P/N	N/A	Special Cleaning?	No	
Service	Compressible	Product Name	LPG Hydrocarbon	Applicable Code	Sec VIII	
Set Pressure	250 PSIG	Total Back Pressure		Cold Diff Set Press	246 PSIG	
Operating Temp	103 F	BP Is / Constant	Constant 4	ASME Capacity	33719 SCFM	
Mfg Lift	IN	Restricted Lift	IN			
Req'd Spring	O645CR	Material	Alloy Steel (CR)	From / To	229 to 260	
Hydro Verified?	Yes	Gauge 1 S/N	PT2	Final Preparation	on Checklist	
Checked-In By	K Joseph	Gge 2/EVT S/N	PT9		Matches Valve	Vec
Parts Inspect By	K Joseph	Final Test Press	249 PSIG		q'ments Check	
Measured Lift	IN	Reseat Press	PSIG	Choin No	Valve Painted	
Disc Rock	IN	Seats Tight @	224		Valve Boarded	Yes
Overlap Collar	IN	BP Test @	Passed @ 30	Client IE	Tag Attached	Yes
Assembled By	K Joseph	Date Tested	2009/11/02	Nameplate/Req'd	Tags Attached	Yes
BD Ring-Up	Notches	Tested By	K Joseph	Replacement Par		
BD Ring-Low	12 Notches	Witnessed By	<u>-</u>		Stamp Applied	
Test Media	Air	Final Inspected By	M Chaisson		stments Sealed	
Test Method	Bench	CI/QC Inspector	K Patrick		lj'd & Strapped Plugs Installed	
		20 mmmlm ages.			Valve Bagged	
Comments			Description	Sp Clean	valve Dagged	IN/A
PRO ASOZO REV 1	6 - MACHINE SPRING WASHERS	\$	Description			

PRO AS070 REV 16 - MACHINE SPRING WASHERS

Valu-Keep II

This historical record is stored in Valv-Keep II For more information contact Carter Chambers



	RELIEF VALVE INSPE	CTION AND SERVICE RECOR	D.
Valve No. PSV-6019	Service_VAPOR	Location	Capacity 33719 31540 Tu
Type. 1910-00PC-2-CC-MS-31-RF-GS-HP	Make CONSOLIDATED	Serial No. SA49635	Set Pressure 250#
Inlet Size 4" 500 97	Outlet Size 6"	Orifice P	Back Pressure
Inlet Conn. FLG RIF	Outlet Cong. The Kin	Spring No. O-645	
, = -		Nozzle SS Spring	C5 Body C5
Materials & Special Feat	Bonnet C	Bellows OzRing	Cap (15

DATE POP TEST AS: REPAIRED REQUIRED	PARTS REQUIREM RESET REPAIR AND REMARKS PARTS USED NEXT OVERHAUL
Jun 27, 2013 O DENALIE	250#
angul AT	VALUE SEALS ZUI STITUSES.
Jun 27, 2013 OpenALLE Spened AT 249	ALSO build-up on intervers.
247	The supplies
Coffing AT	50f 250 C.S. 246 Good
184	507 180
	Azrion Tight 222
	B.P. Testad Good.

(1) Disassemble, Chemically Clean Parts, Inspect Parts, Machine Parts as Required, Lap Nozzle and Disc, Assemble. Test, Paint, Install Cap and Nameplate.

INSPECTION CERTIFICATE

225-752-1943

THIS VALVE HAS BEEN INSPECTED, REPAIRED AS REQUIRED, AND SET TO YOUR REQUIREMENTS BY

GULF VALVE SERVICE CO., LLC BATON ROUGE, LOUISIANA

Date: June 27, 2013

Inspected By:

4)

225-753-0811

225-753-3471 ΓΑΧ

GULF VALVE SERVICE CO., LLC

14045 JEFFERSON HWY.

BATON ROUGE, LA 70817

TELEPHONES

P.O. BOX 86180

BATON ROUGE, LA 70879

NIGHTS/SUNDAYS/HOLIDAYS

State and Factory Authorized Service
We Ropair All Makes Of Valves • New Warrante On All Repairs

e Repair All Makes Of Valves • New Warranty On All Repairs 225-767-8660 ConsolubuedO Valve Setung & Siock Distributor info@gulfvalveservice.com Pickup & Delivery Picht Service

1500 LB, STEAM TEST FACILITIES





Consolidated Safety Relief Valve Sizing and Selection Report SRVS6.2 (Build 6.2.0.1056 - 8/18/2009)

7/9/2010

Dresser Inc. - Consolidated Pressure Relief Valves - Alexandria, LA, USA

	Dresser Inc Consolid		valves	- Alexandria, En. OOA
DMC - CARTER CHAMBERS	S, LLC			Customer Information
13949 River Road				
Luling, LA 70070				Name DYNAMIC FUELS
	le St Pierre			Location Geismar, LA
Checked by				Contract
Spec Sheet No				Project
Rev No				
Tag Number	PSV-6019			Valve Number 1
P&ID Number - Location	130-0013			4P6
Valve Type	1910-00PC-2-CC-MS-31-RF-	GS-HD		- 1 0
Gag Required	No	43-111		
Inlet Connection	110			Notes
Specified	4 00 Flg	300#	Rf	
Selected	4 00 Flg	300#	Rf	Valve sizing based on customer required capacity of
Outlet Connection	1 00 1.9	00011		261,217 PPH
Specified	6 00 Flg	150#	Rf	7
Selected	6 00 Flg	150#	Rf	
Sizing Data		.00#		
Design Code	ASME Section VIII			_
Sizing Basis	Fire SRV Calc - Required Car	nacity		-
Fluid	LPG / HYDROCARBON	pacity		-
Fluid State	Gas			
M	44 8000			-
Z	0 6900			
k	1 100			-
C	327			
Kd (vapor) Kd (liquid)	0 975			_
Kb Kw	1 000			
Ksh Kn	1 000	-		
G Density @ P1				
Viscosity Kv				
Overpressure	21 00 %			_
Kc	1 000			
Pressure		l .	·	7
Operating Set	160 00	250 0	00 Psig	_
MAWP	250 00		Psig	
Flowing	317 20		Psia	
Superimposed Minimum	4 00		Psig	_
Superimposed Maximum	4 00		Psig	-
Builtup Total BP	5 00		00 Psig	
Barometric	14 70		Psia	
Temperature				
Operating	103 00	F		7
Relieving	300 00			7
Design	300 00			7
Flow Area				_
Required	8 8371	ın2		
Selected Designation	6 3800		P	
Standard	API Effective	1	-	7
Capacity				7
		l b/hr		
	261.217 0			
Required	261,217 0 188,587 9			
Required Selected	188,587 9	Lb/hr		
Required	188,587 9	Lb/hr SCFM		

Consolidated

Consolidated Safety Relief Valve Sizing and Selection Report SRVS6 2 (Build 6 2.0 1056 - 8/18/2009)

7/9/2010

Dresser Inc. - Consolidated Pressure Relief Valves - Alexandria, LA, USA

Tag Number	PSV-6019		
Valve Number	1		
Contract		Client	DYNAMIC FUELS
Project		Location	Geismar, LA
Valve Type	1910-00PC-2-CC-MS-31-RF-GS-HP		
Gag Required	No		

Equation Used To Size Consolidated Safety Relief Valves

$$A_c = \frac{W\sqrt{T}\sqrt{Z}}{C K_d P_1 \sqrt{M} K_b K_c K_u}$$

$$8.8371 = \frac{261,217.0000 * sqrt(760 0 * 0 6900)}{327 000 * 0 975 * 317 2000 * sqrt(44 8000) * 1 000 * 1.000 * 1.00000000}$$

$$A = 6.3800 \text{ in } 2$$

Vapors or Gases - Mass Flow Rate Sizing (W = lb/hr) Fluid Name - LPG / HYDROCARBON

Consolidated

Consolidated Safety Relief Valve Sizing and Selection Report

SRVS6.2 (Build 6.2 0 1056 - 8/18/2009)

7/9/2010

Dresser Inc. - Consolidated Pressure Relief Valves - Alexandria, LA, USA

Tag Number	PSV-6019		
Valve Number	2		
Contract		Client	DYNAMIC FUELS
Project		Location	Geismar, LA
Valve Type	1910-00NC-2-CC-MS-31-RF-GS-HP		
Gag Required	No		

Equation Used To Size Consolidated Safety Relief Valves

$$A_c = \frac{W\sqrt{T}\sqrt{Z}}{C \ K_d \ P_1 \sqrt{M} K_b \ K_c \ K_u}$$

$$8 8371 = \frac{261,217.0000 * sqrt(760.0 * 0.6900)}{327 000 * 0 975 * 317 2000 * sqrt(44.8000) * 1 000 * 1.000 * 1 00000000}$$

$$A = 43400 \text{ in} 2$$

Vapors or Gases - Mass Flow Rate Sizing (W = lb/hr) Fluid Name - LPG / HYDROCARBON


Consolidated Safety Relief Valve Sizing and Selection Report SRVS6.2 (Build 6.2.0.1056 - 8/18/2009)

Dresser Inc. - Consolidated Pressure Relief Valves - Alexandria, LA, USA

7/9/2010

Tag Number	PSV-6019					
Valve Type	1910-00PC-2-CC-MS-31-RF-G	S-HP			-	
P&ID No - Location	-	Valv	/e Number 1		Client	DYNAMIC FUELS
Spec Sheet Number		Rev	Number		Location	Geismar, LA
Inlet	4 00 in Flg 300#	Rf Area	6 3800	ın2	Contract	
Outlet	6 00 in Flg 150#	Rf			Project	

Certified by Dresser Consolidated



DIMENSIONS &

A 225 4 mm -- 8-7/8 in B 254 0 mm -- 10 in C 1041 4 mm -- 41in D 292 1 mm -- 11-1/2 in S 49 2 mm -- 1-15/16 in Weight 158 8 kg -- 350 lb

BILL OF MATERIALS						
PARTNAME	MATERIAL					
BASE	ASME SA216 WCC CARBON STEEL					
NOZZLŁ	316 STAINLESS STEEL					
ADJ RING PIN GASKET ADJUSTING RING PIN	SOFT IRON					
ADJUSTING RING PIN ADJUSTING RING	316 STAINLESS STEEL					
DISC	316 STAINLESS STEEL 316 STAINLESS STEEL					
DISC RETAINER	INCONEL A-750					
EDUCTOR TUBE	316 STAINLESS STEEL					
DISC HOLDER	316 STAINLESS STELL					
) GUIDE	316 STAINLESS STEEL					
GUIDE GASKET	SOFT IRON					
2 SPINDLE RETAINER	INCONEL X-750					
BONNET GASKET	SOFI IRON					
STUD NUTS	ASME SA194 2H CARBON STEEL					
BASE STUDS	ASME SA193 B7 ALLOY STEEL					
VENT PIPE PLUG	CARBON STEEL					
7 SPRING	ALLOY STEEL					
SPINDLE	410 STAINLESS STEEL					
BONNET	ASME SA216 WCC CARBON STEEL					
SPRING WASHER	CARBON STEEL					
CAP GASNEI	SOFI IRON					
2 ADJUSTING SCREW NUT	416 STAINLESS STEEL					
ADJUSTING SCREW	416 STAINLESS STEEL					
CAP CAP	CARBON STEEL					
O1 SHOWN						
BASE PLUG	CARBON STEEL					

Valve picture is for reference only and is not to scale

Consolidated


Consolidated Safety Relief Valve Sizing and Selection Report SRVS6.2 (Build 6.2.0.1056 - 8/18/2009)

7/9/2010

Dresser Inc. - Consolidated Pressure Relief Valves - Alexandria, LA, USA

Tag Number	PSV-6019				
Valve Type	1910-00NC-2-CC-MS-31-RF-GS-HP				
P&ID No - Location	-	Valve Number	2	Client	DYNAMIC FUELS
Spec Sheet Number		Rev Number		Location	Geismar, LA
Inlet	4 00 in Fig 300# Rf	Area	4 3400 in2	Contract	
Outlet	6 00 in Flg 150# Rf		!- ·-	Project	

Certified by Dresser Consolidated



DIMENSIONS &

B 209 6 mm -- 8-1/4 in C 870 0 mm -- 34-1/4 in D 266 7 mm -- 10-1/2 in S 49 2 mm -- 1-15/16 in Weight 117 9 kg -- 260 lb

A 196 9 mm -- 7-3/4 in

BILL OF MATERIALS

PARTNAME	MATERIAL
1 BASE	ASME SA216 WCC CARBON STEEL
2. NOZZLE	316 STAINLESS STEEL
ADJ RING PIN GASKET	SOFI IRON
4 ADJUSTING RING PIN 5 ADJUSTING RING	316 STAINLESS STEEL 316 STAINLESS STEEL
6 DISC	316 STAINLESS STEEL
7 DISC RETAINER	INCONEL & 750
8 EDUCTOR TUBE	316 STAINLESS STEEL
9 DISC HOLDER	316 STAINLESS STEEL
10 GUIDE	316 STAINLESS STEEL
11 GUIDE GASKET	SOF1 IRON
12 SPINDLE RETAINER	INCONEL A 750
13 BONNET GASKET	SOFI IRON
14 STUD NUTS	ASME SA194 2H CARBON STEEL
15 BASE STUDS 16 VENT PIPE PLUG	ASME SA193 B7 ALLOY STEEL CARBON STEEL
17 SPRING	ALLOY STEEL
18 SPINDLE	410 STAINLESS STEEL
19 BONNET	ASME SA216 WCC CARBON STEEL
20 SPRING WASHER	CARBON STEEL
21 CAP GASKEI	SOFI IRON
22 ADJUSTING SCREW NUT	416 STAINLESS STEEL
23 ADJUSTING SCREW	416 ST AINLESS STEEL
24 CAP	CARBON STEEL
NOT SHOWN	
BASE PLUG	CARBON STEEL
İ	
	1
1	
1	
	Í
	1
L	

Valve picture is for reference only and is not to scale

Consolidated

Consolidated Safety Relief Valve Sizing and Selection Report SRVS6 2 (Build 6 2.0.1056 - 8/18/2009)

7/9/2010

Dresser Inc. - Consolidated Pressure Relief Valves - Alexandria, LA, USA

	Dresser Inc Consolidated Pressure Hellet Valve	s - Alexandria, LA, USA
DMC - CARTER CHAMBERS	S, LLC	Customer Information
13949 River Road		
Luling, LA 70070		Name DYNAMIC FUELS
	le St. Pierre	Location Geismar, LA
Checked by		Contract
Spec Sheet No		Project
Rev No		Tojour
Tag Number	PSV-6019	Valve Number 2
P&ID Number - Location	F3V-6019	4N6
	4040 00NO 0 00 NO 04 DE CO UD	— ⁴¹⁰
Valve Type	1910-00NC-2-CC-MS-31-RF-GS-HP	
Gag Required	No	No.
Inlet Connection	100 51 0001	<u>Notes</u>
Specified	4 00 Flg 300# Rf	-
Selected	4 00 Flg 300# Rf	
Outlet Connection		
Specified	6 00 Flg 150# Rf	_
Selected	6 00 Flg 150# Rf	_
Sizing Data		_
Design Code	ASME Section VIII	
Sizing Basis	Fire SRV Calc - Required Capacity	
Fluid	LPG / HYDROCARBON	
Fluid State	Gas	
М	44 8000	
Z	0 6900	
k	1 100	
С	327	
Kd (vapor) Kd (liquid)	0 975	
Kb Kw	1 000	
Ksh Kn		
G Density @ P1		
Viscosity Kv		
Overpressure	21 00 %	
Кс	1 000	
Pressure		
Operating Set	160 00 250 00 Psig	
MAWP	250 00 Psig	
Flowing	317 20 Psia	
Superimposed Minimum	4 00 Psig	
Superimposed Maximum	4 00 Psig	
Builtup Total BP	5 00 9 00 Psig	
Barometric	14 70 Psia	
Temperature		
Operating	103 00 F	
Relieving	300 00 F	
Design	300 00 F	
Flow Area		
Required	8 8371 In2	
Selected Designation	4 3400 in2 N	
Standard	API Effective	
Capacity		_
Required	261,217 0 Lb/hr	
Selected	128,287 1 Lb/hr	
Nameplate	22,945 SCFM	-
Reaction Force	1,661 lbs	
Noise Level	144 DBa @ 3 ft	
14019E FEAGI		

	RELIEF VALVE INSPE	CTION AND SERVICE RECORI	D
Valve No. PSV-6020	Service VAPOR	Location	Capacity 229455CFM
Type. 1910-00NC-2-CC-MS-31-RF-GS-HP	Make CONSOLIDATED	Serial No. SA55748	Set Pressure 250#
Inlet Size 4" 305	Outlet Size 6"	Orifice N	Back Pressure
Inlet Conn. D. D. T.	Outlet Conn	Spring No. O-393CR	
120 ///	Disc 55 N	lozzle 55 Spring	Of Body 05
Materials & Special Features	Bonnet CS 8	cllews Offing	Cap as

DATE POP TEST AS REPAIRED REQUIRED	PARTS REQID. RESET REPAIR AND REMARKS PARTS USED. NEXT OVERHAUL.
Jun 27, 2013	250# (1) VALUE SEATS CATE PITTED NONE
operal AT	Aso build-up on interness.
248	Complete overhoul soul
Cesting AT	Complete or and the
191	Set 250 " C.S. 245" Good
	Berion Tight 220
	PIP. PESTEU GOOK

(1) Disassemble, Chemically Clean Parts, Inspect Parts, Machine Parts as Required, Lap Nozzle and Disc, Assemble. Test, Paint, Install Cap and Nameplate.

INSPECTION CERTIFICATE

GULF VALVE SERVICE CO., LLC

14045 JEFFERSON HWY. BATON ROUGE, LA 70817 TELEPHONES 225-753-0811

225-753-3471 FAX

INIGHTS/SUNDAYS/HOLIDAYS 225-752-1943 State and Factory Authorized Service We Repair All Makes Of Valves • New Warranty On 4ll Repairs 225-767-8660

Consolulated O Valve Setting & Stock Distributor info@gulfvalveservice.com Pickup & Delivery Field Service



THIS VALVE HAS BEEN INSPECTED, REPAIRED AS REQUIRED, AND SET TO YOUR REQUIREMENTS BY

GULF VALVE SERVICE CO., LLC BATON ROUGE, LOUISIANA

June 27, 2013 Date:

Inspected By







New Pressure Relief Valve Test Report

\$3-Six Sigma Service

Type: SRV



Birth # 003A22

Date Friday, July 09, 2010

Warehouse Date-Time 2010/01/26-16 00

Ship Date-Time 2010/01/28-14 00

Owner Dynamic Fuels Plant Geismar, LA Account # 30657

PO# 4506429249 C/O 4

Tag Number	PSV-6020	Location		Other Tag Data		-
Most Recent	Yes (Relief Valve)	Unit		Client Stock#		
Manufacturer	Consolidated		4 00 N 6 00 = 4 34 IN^2	In/Outlet Rating	300# RF / 150	# RF
Model Number	1910-00NC-2-CC-MS-31-RF-GS-F	IP S/N	SA55748	Cap Type	Screwed Cap	
Soft Seat Mat'l	N/A	Soft Seat P/N	N/A	Special Cleaning?	No	
Service	Compressible	Product Name	LPG Hydrocarbon	Applicable Code	Sec VIII	
Set Pressure	250 PSIG	Total Back Pressure	9 PSIG	Cold Diff Set Press	245 PSIG	
Operating Temp	103 F	BP Is / Constant	Constant 5	ASME Capacity	22945 SCFM	
Mfg Lift	IN	Restricted Lift	IN			
Req'd Spring	O393CR	Material	Alloy Steel (CR)	From / To	236 to 275	
Hydro Verified?	Yes	Gauge 1 S/N	PT9	Final Preparation	on Checklist	
Checked-In By	J Boyle	Gge 2/EVT S/N	PT2		Matches Valve	Vac
Parts Inspect By	J Boyle	Final Test Press	250 PSIG		eq'ments Check	
Measured Lift	=	Reseat Press	PSIG	Chemene	Valve Painted	
Disc Rock	IN	Seats Tight @	225		Valve Boarded	Yes
Overlap Collar	IN	BP Test @	Passed @ 30	Client II	Tag Attached	Yes
Assembled By	J Boyle	Date Tested	2010/01/29	Nameplate/Req'd	Tags Attached	Yes
BD Ring-Up	None Notches	Tested By	J Boyle	Replacement Par		
BD Ring-Low		Witnessed By			Stamp Applied	
Test Media	Air	•	C Austin		stments Sealed	
		Final Inspected By	_	Lever Ac	lj'd & Strapped	N/A
Test Method	Bench	CI/QC Inspector	K Patrick		Plugs Installed	
Comments				Sp Clean	Valve Bagged	N/A
	6 - MACHINE SPRING WASHER:	S	Description	<u> </u>		
nooro nor	S SIMILE DI MING WINDING	-	1			

Valu-Keep II

This historical record is stored in Valv-Keep II For more information contact Carter Chambers

DRESSER Consolidated

Consolidated Safety Relief Valve Sizing and Selection Report Dresser Inc. - Consolidated Pressure Relief Valves - Alexandria, LA, USA

SRVS6 2 (Build 6 2 0 1056 - 8/18/2009)

7/9/2010

Tag Number	PSV-6020		
Valve Number	1		
Contract		Client	DYNAMIC FUELS
Project		Location	Geismar, LA
Valve Type	1910-00PC-2-CC-MS-31-RF-GS-HP		
Gag Required	No		

Equation Used To Size Consolidated Safety Relief Valves

$$A_{c} = \frac{W\sqrt{T}\sqrt{Z}}{C K_{d} P_{1}\sqrt{M}K_{b} K_{c} K_{u}}$$

$$5.5667 = \frac{222,147.0000 * sqrt(838 0 * 0.6300)}{372.000 * 0 975 * 377 7000 * sqrt(44 8000) * 1.000 * 1 0000* 1 00000000}$$

$$A = 6.3800 \text{ in } 2$$

Vapors or Gases - Mass Flow Rate Sizing (W = lb/hr) Fluid Name - LPG / HYDROCARBON

Consolidated


Consolidated Safety Relief Valve Sizing and Selection Report SRVS6.2 (Build 6.2.0.1056 - 8/18/2009)

Dresser Inc. - Consolidated Pressure Relief Valves - Alexandria, LA, USA

7/9/2010

Tag Number	PSV-6020				
Valve Type	1910-00PC-2-CC-MS-31-RF-GS-HP				
P&ID No - Location	-	Valve Number 1		Client	DYNAMIC FUELS
Spec Sheet Number		Rev. Number	-	Location	Geismar, LA
Inlet	4 00 in Flg 300# Rf	Area 6	3800 in2	Contract	
Outlet	6 00 in Flg 150# Rf			Project	

Certified by Dresser Consolidated



DIMENSIONS &

A 225 4 mm -- 8-7/8 in B 254 0 mm -- 10 in C 1041 4 mm -- 41 in D 292 1 mm -- 11-1/2 in S 49 2 mm -- 1-15/16 in Weight 158 8 kg -- 350 lb

BILL OF MATERIALS

PARTNAME	MATERIAL
1 BASE	ASME SA216 WCC CARBON STEEL
2 NOZZLŁ	316 STAINLESS STEEL
3 ADJ RING PIN GASKET	SOFT IRON
4 ADJUSTING RING PIN	316 STAINLESS STEEL
5 ADJUSTING RING	316 STAINLESS STEEL
6 DISC	316 STAINLESS STEEL
7 DISC RETAINER	INCONEL X-750
8 EDUCTOR TUBE	316 STAINLESS STEEL
9 DISC HOLDER	316 STAINLESS STEEL
10 GUIDE	316 STAINLESS STEEL
11 GUIDE GASKET	SOFI IRON
12 SPINDLE RETAINER	INCONEL X-750
13 BONNET GASKET	SOFT IRON
14 STUD NUTS	ASME SA194 2H CARBON STEEL
15 BASE STUDS	ASME SA193 B7 ALLOY STEEL
16 VENT PIPE PLUG	CARBON STEEL
17 SPRING	ALLOY STEEL
18 SPINDLE	410 STAINLESS STEEL
19 BONNET	ASME SA216 WCC CARBON STEEL
20 SPRING WASHER	CARBON STEEL
21 ADJUSTING SCREW NUT	416 STAINLESS STEEL
22 ADJUSTING SCREW	416 STAINLESS STEEL
23 CAP	CARBON STEEL
NOT SHOWN	
BASE PLUG	CARBON STEEL
	į

Valve picture is for reference only and is not to scale

Consolidated

Consolidated Safety Relief Valve Sizing and Selection Report SRVS6 2 (Build 6 2.0.1056 - 8/18/2009)

7/9/2010

Dresser Inc - Consolidated Pressure Relief Valves - Alexandria, LA, USA

	Diessei ilic - Collsolidated Fressu	e Heller Valves -	Alexandria, EA, COA
DMC - CARTER CHAMBERS	S, LLC		Customer Information
13949 River Road			
Luling, LA 70070			Name DYNAMIC FUELS
-	le St Pierre		Location Geismar, LA
Checked by			Contract
Spec Sheet No			Project
Rev No			i rojeci
	DOV 0000		Malan Marahan
Tag Number	PSV-6020		Valve Number 1
P&ID Number - Location			4P6
Valve Type	1910-00PC-2-CC-MS-31-RF-GS-HP		
Gag Required	No		
Inlet Connection			<u>Notes</u>
Specified	4 00 Fig 300#	Rf	
Selected	4 00 Flg 300#	Rf	
Outlet Connection			
Specified	6 00 Flg 150#	Rf	
Selected	6 00 Flg 150#	Rf	
Sizing Data			
Design Code	ASME Section VIII		
Sizing Basis	Fire SRV Calc - Required Capacity		
Fluid	LPG / HYDROCARBON		
Fluid State	Gas		
M	44 8000		
Z	0 6300		
k	1 595		
C	372		
Kd (vapor) Kd (liquid)	0 975		
Kb Kw	1 000		
Ksh Kn	1 000		
Viscosity Kv	04.00.07		
Overpressure	21 00 %		
Kc	1 000		
Pressure			
Operating Set		0 00 Psig	
MAWP	300 00	Psig	
Flowing	377 70	Psia	
Superimposed Minimum	4 00	Psig	
Superimposed Maximum	4 00	Psig	
Builtup Total BP	5 00	9 00 Psig	
Barometric	14 70	Psia	
Temperature			
Operating	103 00 F		
Relieving	378 00 F		
Design	300 00 F		
Flow Area			
Required	5 5667 in2		
Selected Designation	6 3800 in2	Р	
Standard	API Effective		
Capacity			
Required	222,147 0 Lb/hr		
Selected	254,602 1 Lb/hr	<u>-</u>	
Nameplate	40,122 SCFM		
Reaction Force	3,650 lbs		
		2 #	+
Noise Level	149 DBa @	3 ft	



Annual Fire Sprinkler System Inspection

Inspector: Brett Young Inspection Date: 6/15/2015

Inspection conducted at:

REG Geismar

BI15016029 36187 Hwy 30 Geismar LA

Inspection performed in accordance with NFPA 25 Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems, 2011 edition. Individual code references shown in () for this standard.

2485 Burden Lane Mobile, AL 36617 251.473.6000 toll free: 800 443.5897

14054 Jefferson Highway Baton Rouge, LA 70817 225.753 8512 toll free: 888 432 8512

3601 Highway 90 Westlake, LA 70669 337 882 0000 toll free: 877 746.5537 2150 Wellspring Drive Beaumont, TX 77705 409 729 444 toll free. 800.222.1204



Administrative intermetten

Gretomer/Address	Inspection Location
REG Geismar	REG Geismar
416 S Bell Ave.	36187 Hwy 30
Ames, IA 50010	Geismar, LA 70734
	Phone: (225) 744-1306
Inspection Date: 6/15/2015	Contact ⁻ Mr Wilkinson

Building owner / representative	
Is building currently occupied?	Yes
Has building occupancy, hazard, water supply or building arrangement affecting system effectiveness remained the same since last inspection? (4 1 6 1)	Yes
Are all fire protection systems in service? (4 5 4)	Yes
Was system free of actuations or alarms since last inspection?	Yes
Owner/Representative Signature How and William	vertramentikken melakerkommungkak demo "in 1600 keptuar pung 140 - pulat menjungkangunund

			《新兴教》	
on a recognity (Helphald Alexandra Angula and)	ems	Charles was a series of the se	Landard Control Control	Total Systems
Deluge System				1
Wet System]	2
The second secon			Total	5

Chtrl VIv (Del) - sealed	n
HDO Solvent Recycle Pumps Victaulic Series 728	
Valve type?	Butterfly
What is valve size?	2 5"
Valve has proper signs, and is accessible? (13 3 2 2)	Yes
Valve is free of external leaks, and appropriate wrench available? (13 3 2 2)	Yes
Valve in normal open or closed position? (13 3 2 2)	No
Valve properly sealed? (13 3 2 2)	Yes
Valve lubnicated, if required, and exercised through full range to ensure proper operation? (13 3 3 1)	Yes
HDO Solvent Recycle Pumps	
Sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage, and heads installed in proper orientation? (5 2 1 1 1)	Yes
Sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage and heads installed in proper onentation? (5 2 1 1 1) Minimum clearance maintained below all sprinklers? (5 2 1 2)	Yes Yes
Sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage, and heads installed in proper orientation? (5 2 1 1 1) Minimum clearance maintained below all sprinklers? (5 2 1 2) Number of replacement sprinkler heads per number installed in the head box comply 6 per 1-300, 12 per 301 to 1,000	
Sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage, and heads installed in proper orientation? (5 2 1 1 1) Minimum clearance maintained below all sprinklers? (5 2 1 2) Number of replacement sprinkler heads per number installed in the head box comply 6 per 1-300, 12 per 301 to 1,000, 24 per > 1,000? (5 4 1 5) Sprinkler head wrench for each type head provided in head box? (5 4 1 6)	Yes
Sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage, and heads installed in proper onentation? (5 2 1 1 1) Minimum clearance maintained below all sprinklers? (5 2 1 2) Number of replacement sprinkler heads per number installed in the head box comply 6 per 1-300, 12 per 301 to 1,000, 24 per > 1,000? (5 4 1 5) Sprinkler head wrench for each type head provided in head box? (5 4 1 6) System piping free of mechanical damage, leaks, corrosion, misalignment, or other loads or pipe hung from system?	Yes Yes
Sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage, and heads installed in proper onentation? (5 2 1 1 1) Minimum clearance maintained below all sprinklers? (5 2 1 2) Number of replacement sprinkler heads per number installed in the head box comply 6 per 1-300, 12 per 301 to 1,000, 24 per > 1,000? (5 4 1 5) Sprinkler head wrench for each type head provided in head box? (5 4 1 6) System piping free of mechanical damage, leaks, corrosion, misalignment, or other loads or pipe hung from system? (5 2 2 1, and 5 2 2 2)	Yes Yes Yes
Sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage, and heads installed in proper orientation? (5 2 1 1 1) Minimum clearance maintained below all sprinklers? (5 2 1 2) Number of replacement sprinkler heads per number installed in the head box comply 6 per 1-300, 12 per 301 to 1,000, 24 per > 1,000? (5 4 1 5) Sprinkler head wrench for each type head provided in head box? (5 4 1 6) System piping free of mechanical damage, leaks, corrosion, misalignment, or other loads or pipe hung from system? (5 2 2 1, and 5 2 2 2) Pipe hangers and seismic braces secure and undamaged? (5 2 3 1)	Yes Yes Yes
Sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage, and heads installed in proper orientation? (5 2 1 1 1) Minimum clearance maintained below all sprinklers? (5 2 1 2) Number of replacement sprinkler heads per number installed in the head box comply 6 per 1-300, 12 per 301 to 1,000, 24 per > 1,000? (5 4 1 5) Sprinkler head wrench for each type head provided in head box? (5 4 1 6) System piping free of mechanical damage, leaks, corrosion, misalignment, or other loads or pipe hung from system? (5 2 2 1, and 5 2 2 2) Pipe hangers and seismic braces secure and undamaged? (5 2 3 1) Adequate heat to protect part of system containing water at a minimum temperature of 40° F? (4 1 1 1)	Yes Yes Yes Yes Yes
Sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage and heads installed in proper onentation? (5 2 1 1 1) Minimum clearance maintained below all sprinklers? (5 2 1 2) Number of replacement sprinkler heads per number installed in the head box comply 6 per 1-300 12 per 301 to 1,000 24 per > 1,000? (5 4 1 5) Sprinkler head wrench for each type head provided in head box? (5 4 1 6) System piping free of mechanical damage, leaks, corrosion, misalignment, or other loads or pipe hung from system? (5 2 2 1 and 5 2 2 2) Pipe hangers and seismic braces secure and undamaged? (5 2 3 1) Adequate heat to protect part of system containing water at a minimum temperature of 40° F? (4 1 1 1) All sprinklers in this building been manufactured after 1920? (5 3 1 1 1 1) Sprinklers in building are less than 50 years old, or if older has sprinkler sample been tested? (5 3 1 1 1)	Yes Yes Yes Yes Yes Yes Yes

REG Geismar

Deluge valve	
HDO Solvent Recycle Pumps Firelock NXT 2" S/769	
Vater pressure gauge operating properly? (5 2 4 2)	Yes
System control valve have proper signs, accessible and free of leaks, has appropriate wrench and properly secured? 13 3 2 2)	Yes
System control valve in normal open/closed position? (13 3 2 2)	No
Pressure (psi) shown on Water Supply pressure gauge. (13 4 3 1 3 1)	0
xtenor in good condition, all trim valves in normal position, valve seat not leaking and any electrical parts in service?	Yes
/alve enclosure and heating equipment, during cold weather, maintain 40° F temperature? (13 4 3 1 1)	Yes
orain Size	3/4"
hydraulic nameplate, if applicable, securely attached to sprinkler system and is legible? (5 2 6)	Yes
s there adequate drainage available? (13 2 4)	N/A
Water Motor Alarm - mechanical (Del)	
HDO Solvent Recycle Pumps Victaulic	
Nater motor alarm free of damage? (5 2 5)	Yes
Nater flow activate alarm when open test connection/bypass? (5 3 3 3)	N/A
14/-4 Dun	to the contract of the contrac
Water Pressure Switch (Del)	1
HDO Solvent Recycle Pumps System Sensor EPS-10-2	
Oid the switch pass a visual inspection conducted in accordance with manufacturer's requirements?	Yes
Did the switch pass operational tests when pressure is increased?	No
Cntrl VIv (Del) - sealed HI Charge Pumps Victaulic Series 728	
Valve type?	Butterfly
What is valve size?	25"
/alve has proper signs, and is accessible? (13 3 2 2)	Yes
/alve is free of external leaks, and appropriate wrench available? (13 3 2 2)	Yes
/alve in normal open or closed position? (13 3 2 2)	No
Valve properly sealed? (13 3 2 2)	Yes
Valve lubricated, if required, and exercised through full range to ensure proper operation? (13 3 3 1)	Yes
Deluge System Inspection	ı
HI Charge Pumps	
sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage, and heads installed in proper principle.	Yes
Minimum clearance maintained below all sprinklers? (5 2 1 2) Number of replacement sprinkler heads per number installed in the head box comply 6 per 1-300 12 per 301 to 1,000	Yes Yes
24 per > 1,000? (5 4 1 5) Sprinkler head wrench for each type head provided in head box? (5 4 1 6)	Yes
System piping free of mechanical damage, leaks, corrosion, misalignment, or other loads or pipe hung from system?	AND A LOS ASSESSED SOUTHERN AND A SECOND SEC
5221 and 5222)	Yes
Pipe hangers and seismic braces secure and undamaged? (5 2 3 1)	No No
Adequate heat to protect part of system containing water at a minimum temperature of 40° F? (4 1 1 1)	Yes
All sprinklers in this building been manufactured after 1920? (5 3 1 1.1 1)	Yes
	Yes
Sprinklers in building are less than 50 years old, or if older has sprinkler sample been tested? (5 3 1 1 1) If fast response sprinklers in building are 20 years old or older has sprinkler sample been tested? (5 3 1 1 1 3)	163

Deluge valve	
HI Charge Pumps Firelock NXT 2" S/769	
Nater pressure gauge operating properly? (5 2 4 2)	Yes
System control valve have proper signs, accessible and free of leaks, has appropriate wrench and properly secured? 13 3 2 2)	Yes
System control valve in normal open/closed position? (13 3 2 2)	No
Pressure (psi) shown on Water Supply pressure gauge (13 4 3 1 3 1)	0
extenor in good condition, all trim valves in normal position, valve seat not leaking and any electrical parts in service? 13 4 3 1 6)	Yes
/alve enclosure and heating equipment, during cold weather, maintain 40° F temperature? (13 4 3 1 1)	N/A
Orain Size	3/4"
lydraulic nameplate, if applicable, securely attached to sprinkler system and is legible? (5 2 6)	Yes
s there adequate drainage available? (13 2 4)	N/A
Water Motor Alarm - mechánical (Del)	
Water motor alarm free of damage? (5 2 5)	Yes
Nater flow activate alarm when open test connection/bypass? (5 3 3 3)	N/A
The state of the s	
Water Pressure Switch (Del)	
HI Charge Pumps System Sensor EPS-10-2	
Did the switch pass a visual inspection conducted in accordance with manufacturer's requirements?	Yes
Did the switch pass operational tests when pressure is increased?	No No
Air Maintenance Device (Del)	
L-Con Bullets Victaulic	1
Automatic air maintenance device pressure maintained at proper setting for system? (13 4 3 2 15)	Yes
Air Pressure Alarm Device (Del)	
L-Con Bullets Potter-Roemer PS-40-2	
Pressure (psi) shown on the Supervisory Air Pressure gauge (13 4 3 2 13)	30
Low air pressure alarm operates? (13 4 3 2 13)	No No
If installed, is air system air dryer operational? (5 4 2 3)	N/A
Cntrl VIv (Del) - sealed	S. Carlotte
L-Con Bullets Mueller	
Valve type?	OS and Y
What is valve size?	6"
Valve has proper signs, and is accessible? (13 3 2 2)	Yes
Valve is free of external leaks, and appropriate wrench available? (13 3 2 2)	Yes
Valve in normal open or closed position? (13 3 2 2)	Yes
Valve properly sealed? (13 3 2 2)	Yes
	L

REG Geismar Page 4 of 12

Deluge System Inspection	-
L-Con Bullets	
Sprinkler heads free of corrosion, foreign material, paint or damage, no signs of leakage and heads installed in proper onentation? (5 2 1 1 1)	Yes
Minimum clearance maintained below all sprinklers? (5 2.1 2)	Yes
Number of replacement sprinkler heads per number installed in the head box comply 6 per 1-300 12 per 301 to 1,000 24 per > 1,000? (5 4 1 5)	Yes
Sprinkler head wrench for each type head provided in head box? (5 4 1 6)	Yes
System piping free of mechanical damage, leaks, corrosion, misalignment, or other loads or pipe hung from system? (5 2 2 1 and 5 2 2 2)	Yes
Pipe hangers and seismic braces secure and undamaged? (5 2 3 1)	Yes
Adequate heat to protect part of system containing water at a minimum temperature of 40° F? (4 1 1 1)	Yes
All spnnklers in this building been manufactured after 1920? (5 3 1 1 1.1)	Yes
Sprinklers in building are less than 50 years old, or if older has sprinkler sample been tested? (5 3 1 1 1)	Yes
If fast response sprinklers in building are 20 years old or older has sprinkler sample been tested? (5 3 1 1 1 3)	N/A
Deliver vieles	<u> </u>
Deluge valve	
L-Con Bullets Firelock NXT 6" S/769	
Water pressure gauge operating properly? (5 2 4 2)	Yes
System control valve have proper signs, accessible and free of leaks, has appropriate wrench and properly secured?	Yes
(13 3 2 2) System control valve in normal open/closed position? (13 3 2 2)	Yes
Pressure (psi) shown on Water Supply pressure gauge (13 4 3 1 3 1)	160
Extenor in good condition, all trim valves in normal position, valve seat not leaking and any electrical parts in service? (13 4 3 1 6)	Yes
Valve enclosure and heating equipment, during cold weather, maintain 40° F temperature? (13 4 3 1 1)	Yes
Drain Size	2"
Hydraulic nameplate, if applicable, securely attached to sprinkler system and is legible? (5 2 6)	Yes
Is there adequate drainage available? (13 2 4)	
Internal inspection - all components operate properly and move freely, and valve cleaned and in good condition? (13 4 3 1 7)	Yes N/A
Trip test conducted with control valve fully opened? (13 4 3 2 2)	Yes
Pressure (psi) on supply side before start of test (13 4 3 1 3 1)	160
Under test conditions, heat detection system operated within 40 sec, or the flammable gas detection operate within time frame specified in system design? (10 3 4 1 1 and 10 3 4 1 2)	Yes
Time (sec) between start of detection system test and operation (10 3 4 1 3)	5
Time lapse (sec) between operation of detection system and water delivery to protected area (10 3 4 2)	12
Water spray discharge from nozzles flowing freely, positioned properly, and not obstructed? (13 4 3 2 2 3)	Yes
Pressure (psi) at hydraulically most remote nozzle dunng test (13 4 3 2 6 1)	0
Pressure (psi) at the deluge valve during test (13 4 3 2 6 2)	130
Full flow test pressure readings from hydraulically most remote nozzle and valve compare favorably to system requirements? (13 4 3 2 6 3)	N/A
System activated using the manual actuation devices? (13 4 3 2 8)	Yes
Maintenance performed on system after full flow test to ensure properly returned to service? (13 4 3 2 9)	Yes
Auxiliary drains operated and tested for leaks? (13 4 3 3 3)	Yes
Low temperature alarm, if installed in valve enclosure, tested before start of cold season? (13 4 3 2 13)	N/A
I I	Companie
Electric bell (Del)	•
L-Con Bullets Potter-Roemer 120 VAC	
Electric bell operating properly and free of damage? (5 3 3 1)	Yes
Water Pressure Switch (Del)	,
L-Con Bullets Potter-Roemer PS-10-2	
Did the custoh page a viewal improvious conducted in accordance with many factorized and viewall and v	Yes
Did the switch pass a visual inspection conducted in accordance with manufacturer's requirements?	

REG Geismar Page 5 of 12

Cntrl VIv (Del) - sealed	
L-Con Finishing Building Clow 1992	
Valve type?	OS and Y
What is valve size?	4"
Valve has proper signs, and is accessible? (13 3 2 2)	Yes
Valve is free of external leaks, and appropriate wrench available? (13 3 2 2)	Yes
Valve in normal open or closed position? (13 3 2 2)	Yes
Valve properly sealed? (13 3 2 2)	Yes
Valve lubricated, if required, and exercised through full range to ensure proper operation? (13 3 3 1)	Yes
Cntrl VIv (Del) - sealed	
Cntrl Viv (Del) - sealed	
Cntrl Viv (Del) - sealed L-Con Staging Warehouse Clow 1992	f
Cntrl VIv (Del) - sealed L-Con Staging Warehouse Clow 1992 Valve type?	OS and Y
Cntrl Viv (Del) - sealed L-Con Staging Warehouse Clow 1992 Valve type? What is valve size?	OS and Y
Cntrl Viv (Del) - sealed L-Con Staging Warehouse Clow 1992 Valve type? What is valve size? Valve has proper signs, and is accessible? (13 3 2 2)	OS and Y 6" Yes
Cntrl Viv (Del) - sealed L-Con Staging Warehouse Clow 1992 Valve type? What is valve size? Valve has proper signs, and is accessible? (13 3 2 2) Valve is free of external leaks, and appropriate wrench available? (13 3 2 2)	OS and Y 6" Yes Yes

Cntrl VIv (Wet) sealed	, ,
Lab By Maintenance Shop Mueller	•
/alve type?	OS and Y
Vhat is valve size?	6"
'alve has proper signs, and is accessible? (13 3 2 2)	Yes
/alve is free of external leaks, and appropriate wrench available? (13 3 2 2)	Yes
/aive in normal open or closed position? (13 3 2 2)	Yes
/aive properly sealed? (13 3 2 2)	Yes
/alve lubricated, if required, and exercised through full range to ensure proper operation? (13 3 3 1)	Yes
Electric bell (Wet) Lab By Maintenance Shop Potter-Roemer 120 VAC	
Electric bell operating properly and free of damage? (5 3 3 1)	Yes
The same of the sa	
Wet Riser Main Drain/Check Valve	
Lab By Maintenance Shop Victaulic 2 1/2" 717HR	
Extenor of valve in good condition and both gauges operable? (5 2 4 1 and 13 4 1 1)	Yes
Pressure (psi) shown on System side pressure gauge	160
Pressure (psi) shown on Water Supply pressure gauge	160
Orain Size	1 1/4"
Hydraulic nameplate, if applicable, securely attached to sprinkler system and is legible? (5 2 6)	Yes
s there adequate drainage available? (13 2 4)	Yes
Wet System Inspection	'a.t.'
Lab By Maintenance Shop	
Sprinkler heads appear free of corrosion, foreign material, paint or damage, no signs of leakage and heads/deflectors installed in proper orientation? (5.2.1.1)	Yes
Minimum clearance maintained below all sprinklers? (5 2 1 2)	Yes
replacement sprinkler heads per number installed in the head box comply 6 per 1-300 12 per 301 to 1,000 24 per > 1,000 (5 4 1 5)	Yes
Sprinkler head wrench for each type head provided in head box? (5 4 1 6)	Yes
System piping and fittings free of mechanical damage, leaks, corrosion, misalignment, or other loads or pipe hung from system? (5 2 2)	Yes
Pipe hangers and seismic braces secure and undamaged? (5 2 3)	Yes
Adequate heat to maintain minimum building temperature of 40° F, and building free of conditions exposing pipe to reezing? (4 1 1 1)	Yes
All sprinklers in building appear to be manufactured after 1920? (5 3 1 1 1 1)	Yes
Sprinklers in building are less than 50 years old, or if older has sprinkler sample been tested? (5 3 1 1 1)	Yes
If fast response sprinklers in building are 20 years old or older has sprinkler sample been tested? (5 3 1 1 1 3)	N/A
If dry sprinklers are installed in building, and have been in service for 10 years, has sprinkler sample been tested? (5 3 1 1 1 6) Date tested, if applicable	N/A

Alarm Valve	
L-Con Finishing Building Victaulic 4" 751	
Vater pressure gauges operating properly? (13 4 1 1)	Yes
ressure (psi) shown on Water Supply pressure gauge	160
ressure (psi) shown on System side pressure gauge	160
xtenor of valve in good condition all trim valves in normal position, valve seat not leaking and any electrical parts in ervice? (13 4 1 1)	Yes
ystem control valve have proper signs, is accessible and free of leaks, has appropriate wrench and properly ecured? (13 4 1 1)	Yes
tetard chamber and alarm drains free from leakage? (13 4 1 1)	Yes
rain Size	2"
lydraulic nameplate, if applicable, securely attached to sprinkler system and is legible? (5 2 6)	Yes
s there adequate drainage available? (13 2 4)	Yes
Water Motor Alarm - mechanical (Wet)	-
L-Con Finishing Building Victaulic 760	
Nater motor alarm free of damage? (5 2 5)	Yes
Vater flow activate alarm when open test connection/bypass? (5 3 3 3)	Yes
Wet System Inspection	_
L-Con Finishing Building	
Sprinkler heads appear free of corrosion, foreign material, paint or damage, no signs of leakage and heads/deflectors installed in proper orientation? (5.2.1.1)	Yes
finimum clearance maintained below all sprinklers? (5 2 1 2)	Yes
replacement sprinkler heads per number installed in the head box comply 6 per 1-300 12 per 301 to 1,000 24 per > ,000? (5 4 1 5)	Yes
prinkler head wrench for each type head provided in head box? (5 4 1 6)	Yes
System piping and fittings free of mechanical damage, leaks, corrosion, misalignment, or other loads or pipe hung from system? (5.2.2)	Yes
Pipe hangers and seismic braces secure and undamaged? (5 2 3)	Yes
Adequate heat to maintain minimum building temperature of 40° F, and building free of conditions exposing pipe to reezing? (4 1 1 1)	Yes
All sprinklers in building appear to be manufactured after 1920? (5 3 1 1 1 1)	Yes
Sprinklers in building are less than 50 years old, or if older has sprinkler sample been tested? (5 3 1 1 1)	Yes
f fast response sprinklers in building are 20 years old or older has sprinkler sample been tested? (5 3 1 1 1 3)	N/A
f dry sprinklers are installed in building, and have been in service for 10 years, has sprinkler sample been tested? 5 3 1 1 1 6) Date tested, if applicable	N/A
Alarm Valve L-Con Staging Warehouse Victaulic 6"751	Same Part of the State of the S
Water pressure gauges operating properly? (13 4 1 1)	Yes
Pressure (psi) shown on Water Supply pressure gauge	160
Pressure (psi) shown on System side pressure gauge	160
Exterior of valve in good condition all trim valves in normal position, valve seat not leaking and any electrical parts in service? (13 4 1.1)	Yes
System control valve have proper signs, is accessible and free of leaks, has appropriate wrench and properly secured? (13 4 1 1)	Yes
Retard chamber and alarm drains free from leakage? (13 4 1 1)	Yes
Orain Size Welling is well-remained to the control of the control	2"
Hydraulic nameplate, if applicable, securely attached to sprinkler system and is legible? (5 2 6)	Yes
s there adequate drainage available? (13 2 4)	Yes
Water Motor Alarm - mechanical (Wet)	, S.,
L-Con Staging Warehouse Victaulic 760	
Water motor alarm free of damage? (5 2 5)	Yes
Water flow activate alarm when open test connection/bypass? (5 3 3 3)	Yes

REG Geismar Page 8 of 12

Wet System Inspection	
L-Con Staging Warehouse	
Sprinkler heads appear free of corrosion, foreign material, paint or damage, no signs of leakage and heads/deflectors installed in proper orientation? (5.2.1.1)	Yes
Minimum clearance maintained below all sprinklers? (5 2 1.2)	Yes
# replacement sprinkler heads per number installed in the head box comply 6 per 1-300 12 per 301 to 1,000 24 per > 1,000 (5 4 1 5)	Yes
Spnnkler head wrench for each type head provided in head box? (5 4 1 6)	Yes
System piping and fittings free of mechanical damage, leaks, corrosion, misalignment, or other loads or pipe hung from system? (5.2.2)	Yes
Pipe hangers and seismic braces secure and undamaged? (5 2 3)	Yes
Adequate heat to maintain minimum building temperature of 40° F, and building free of conditions exposing pipe to freezing? (4 1 1 1)	Yes
All sprinklers in building appear to be manufactured after 1920? (5 3 1 1 1 1)	Yes
Sprinklers in building are less than 50 years old, or if older has sprinkler sample been tested? (5 3 1 1 1)	Yes
If fast response sprinklers in building are 20 years old or older has sprinkler sample been tested? (5 3 1 1 1 3)	N/A
If dry sprinklers are installed in building, and have been in service for 10 years, has sprinkler sample been tested? (5 3 1 1 1 6) Date tested, if applicable	N/A

REG Geismar Page 9 of 12

Main Drain Te		100					
Туре	Area/Location	Pipe Sıze	Static	Residual	Return pressure	Time (secs.) return static pressure	Without reduction of flow
Wet Riser Main Drain/Check Valve	Lab By Maintenance Shop	1 1/4"	160	150	160	1	Yes
Alarm Valve	L-Con Finishing Building	2"	160	150	160	1	Yes
Alarm Valve	L-Con Staging Warehouse	2 "	160	150	160	1	Yes
Deluge valve	HDO Solvent Recycle Pumps	3/4"	0	0	0	0	N/A
Deluge valve	HI Charge Pumps	3/4"	0	0	0	0	N/A
Deluge valve	L-Con Bullets	2"	160	150	160	1	Yes

Supervisory Devices				
Туре	Area Location	Address	Testing	Visual Inspection
Waterflow Alarm Switch	Lab By Maintenance Shop	M million cardin (c. processor) processor (c. pr. p. process	Pass	Yes
Waterflow Alarm Switch	L-Con Staging Warehouse		Fail 放	Yes
Waterflow Alarm Switch	L-Con Finishing Building	- A POSTO OF STATE OF	Fail 🕡	Yes

1) New Gongs inistalled 8/14/15 Locally. OAN Tested Good 100

Deficiencies
Waterflow Alarm Switch
L-Con Finishing Building Potter-Roemer VSR
Water flow activate alarm when open test connection/bypass? (5.3.3) Answer: Fail - Older Gong - Ordered NEW ONE,
Tech Response Alarm not wired - Gong installed And TESTEDIN the Field DOAL Alarm ON 19 Control Viv (Del) - sealed
HDO Solvent Recycle Pumps Victaulic Series 728
Valve in normal open or closed position? (13.3.2.2) Answer No-System 130 Later - Pierre Damageo, 1st Fire
Tech Response
Waterflow Alarm Switch
L-Con Staging Warehouse Potter-Roemer VSR
Water flow activate alarm when open test connection/bypass? (5.3.3) Answer Fail . Replaced Gous AND TESTED
Tech Response Alarm not wired - LOCAL Alarm Couly (Golfs)
Water Pressure Switch (Del)
HDO Solvent Recycle Pumps System Sensor EPS-10-2
Did the switch pass operational tests when pressure is increased? Answer No. System ISOlated - Point Fire Damage
Tech Response Switch not wired . Local TRIP _ Could not Test_ Pipe Bush
Deluge System Inspection OPEN END
HI Charge Pumps
Pipe hangers and seismic braces secure and undamaged? (5.2.3.1) Answer No
Tech Response Hanger off on 2" main on corner of building . FIRE DAMAGE to Pipracy From 4/2 FIRE
Air Pressure Alarm Dévice (Dél)
L-Con Bullets Potter-Roemer PS-40-2 Low air pressure alarm operates? (13.4.3.2.13) Answer No LOCAL Goods + K++++ L-Con Bullets Potter-Roemer PS-40-2 Low air pressure alarm operates? (13.4.3.2.13) Answer No LOCAL Goods + K++++ L-Con Bullets Potter-Roemer PS-40-2
Low air pressure alarm operates? (13.4.3.2.13) Answer: No Local Gong + C++Co Tech Response Alarm not wired
Deluge valve
HDO Solvent Recycle Pumps Firelock NXT 2" S/769
System control valve in normal open/closed position? (13.3.2.2) Answer No System Isolated Because of 4/2 Fire
Tech Response System off due to the removal of the Solvent Recycle Pumps
Deluge valve
HI Charge Pumps Firelock NXT 2" S/769
System control valve in normal open/closed position? (13.3 2.2) Answer No System Isolate Because of 4/2/15 Fi
Tech Response Valve is blocked in due to leak on system (operations)
Water Pressure Switch (Del)
HI Charge Pumps System Sensor EPS-10-2
Did the switch pass operational tests when pressure is increased? Answer No Signal Isolates Because of 42/5 Fine
Tech Response Switch not wired
Cntrl VIv (Del) - sealed
HI Charge Pumps Victaulic Series 728
Valve in normal open or closed position? (13.3.2.2) Answer No System Isolated Beenise of 4/2/15 Fire
Tech Response
Notes: 8/14/15 HARMS
NOTES: 8/14/19 1) All FIRE WATER STATIONS HAME local gongs installed 2) FIRE DAMASE PREVENTED Systems From Found tester in the operating Areas.
2) FIRE DAMASE PREVENTED SYSTEMS FROM FOUND 1
+ the OPERATING AIREAS!
in the operations that will kinn
1/1/1/2/ WW Rum

Liability Release Statement
The owner and/or designated representative acknowledges the responsibility of the operating condition of the component parts at the time of this inspection. It is agreed that the inspection service provided by the contractor as prescribed herein is limited to performing a visual inspection and/or routine testing, and any investigation or unscheduled testing, modification, maintenance, repair, etc., of the component parts is not included as part of the inspection work performed. It is further understood that all information contained herein is provided to the best of the knowledge of the party providing such information.

Howard	6/15/15	J.		6/15/15
MANAGEMENT OF THE PROPERTY OF		April Market State of the Control of	THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER OF THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	
Customer: Howard Wilkinson		Technician	Brett Young	